## Risk Management Guidelines for New and Modified Sources

ARB Environmental Justice Stakeholders Meeting

March 24, 2003



California Environmental Protection Agency
Air Resources Board

#### **Toxics New Source Review**

- ? Health and Safety Code 39666 (e) requires local air district new source review (NSR) rules and regulations to control emissions of toxic air contaminants (TACs)
- ? Several districts have formal toxics NSR rules, most others have policies
- ? ARB has no direct authority for permitting new stationary sources of TACs

# Risk Management Guidelines Background

- ? Approved in 1993
- ? Guidance not regulatory
- ? Provides information on basic risk assessment and risk management
- ? Assists districts in making permitting decisions for new and modified sources of TACs
- ? Districts may be more or less stringent than suggested guidance

#### What the Guidelines do

- ? Specific risk levels trigger technology requirements
- ? Specifies action range for permit approval
- ? Action range is suggested to provide flexibility for considerations of other factors in making permit decisions
- ? Provides for both cancer and noncancer impacts

## **Key Terms**

- ? Permit Unit
- ? Project
- ? Source
- ? Risk Levels
- ? T-BACT
- ? Specific Findings Report

#### **New and Modified Sources**

**Entire Source Risk Evaluation Required\*** 

